

Thread BSP Parallel

Technical drawing of the mechanical assembly showing dimensions L_1 , L_2 , A , B , and labels CH1, CH2, O-ring, and a 60° angle.

Series BS	30.... [bar]	31.... [bar]	Ordering Complete	A	B	L1	L2	CH1	CH2
UNIVERSAL	350	350	305801	1/8	1/8	21	26	11	14
			305802	1/4	1/8	26	30	14	14
	315	315	305803	1/4	1/4	26	32	14	19
			305804	3/8	1/4	29	37	19	19
	250	250	305805	3/8	3/8	29	37	19	22
			305806	1/2	3/8	34	39	22	22
			305807	1/2	1/2	34	43	22	30
			305808	3/4	1/2	41	47	27	30
			305809	3/4	3/4	41	49	27	36
			305810	1	3/4	45	50	33	36
			305811	1	1	45	52	33	41
	200	200	305812	1 1/4	1	52	58	41	41
			305813	1 1/4	1 1/4	52	58	41	50
			305814	1 1/2	1 1/4	59	59	48	50
	160	160	305815	1 1/2	1 1/2	59	60	48	55
			305816	2	1 1/2	78	74	65	55
	125	125	305817	2	2	78	74	65	70

Notes: If you wish to order a fitting in stainless steel, please change the first two digit from **30....** to **31....** .